




**PUBLIC HEALTH LABORATORY OF JOHOR  
BAHRU  
MINISTRY OF HEALTH**


Doc No: A03-001(ii)  
Issue No: 1  
Issue Date: 15<sup>th</sup> January 2009  
Effective Date : 1<sup>st</sup> February 2009  
Issue By: Quality Manager  
Rev. No: 0  
Page No: 1 of 1

**APPENDIX 2**  
(SOP Handling of Test Items)  
**PROCEDURE OF PACKING SAMPLE IN ICEBOX**

- A) The sample separated in ice, no hot spot Occurred, enhance rapid cooling and Easy flows for melting ice.



- B) Occurrence of Hot Spot



NOTE: Hot spot is being occurred due to:-

- The amount and size of ice are too big and not enough to control the temperature inside the box
- The overlapping sample
- There are too many sample
- Sample touch to an ice box
- The big air space in packaging